## **Crew Chief Summary:** 5-24-06 Day shift Short control access into booster, mi and f sector Pbar safety system and ps test Tev contol access most of day B11 sep work S&S of Numi, minos and decay pipe Eve Numi SS test eary D:IB B11 sep work continues Pbar PT, PB and Rings Ps tunred on Tev sep conditioning MI beam studies Owls Tev HFU Booster, Mi, Tev prepared for controlled access **Notes from Integration:** MI made progress • Gearing up toward Pbar getting beam F-Sector - P2 line work Limited access in Tev due to walkthrough. **Machine Summaries: Mech Support** B11 passing all vacuum leak tests. Get to 10-9 to sublimate. If can get to 10-10, won't have to bake? But we may bake no matter what. F-Sector work - change gauge in F1 TEL1 and 2. Need to verify equipment is out of Tev. Linac Summary: Linac steering study □ NTF at 9am □ 1030am - 55 LCW system. Requests: П **Booster** Summary: Access - ORBMP shunts disconnected Out by 10am, then PS tests in ORBMP. Still at 1 to 2 turns. Requests: **Main Injector** Summary: Better day yesterday Changed mode dampening resistor that was part of transducer

Only two quad moves in vertical plane.

Evening shift, went to 150Gev, got coalescing working.

□ Shunt repairs in MI8 good.

circuit.

	<ul> <li>Will start trying to supply beam to users.</li> </ul>
	■ Requests:
0	Pbar
	Summary:     Ohio working on D.IR
	<ul><li>Obie working on D:IB</li><li>Pbar target is ready for beam.</li></ul>
	□ Problems
	♦ Q109 needs repairs
	<ul> <li>Deb beam valve 309 (is open)</li> </ul>
	□ Access
	OTR cabling - cabling up to F23 is mis-wired.
	□ Plan -
	<ul> <li>Mock recycler transfers.</li> </ul>
	<ul> <li>Start reverse proton work to establish beam to the Debuncher.</li> </ul>
	<ul><li>PreVault access work</li><li>OTR work</li></ul>
	□ Sump float
	<ul> <li>Beam valve near OTR does not have status readback.</li> </ul>
	Requests:
0	Tevatron
	• Summary:
	□ Tomorrow for signoffs
	<ul> <li>Attempt to power Tev tomorrow and run power supplies over the</li> </ul>
	weekend.
	□ Linux sequencer tests. ■ Requests:
0	Recycler
	• Summary:
	<ul><li>Lost a bulk supply -</li><li>Ecool working on leak checking - leaks getting smaller.</li></ul>
	Ecool working on leak checking - leaks getting smaller.      Proton lifetime was 5000 hrs
	• Requests:
0	SY120
	<ul><li>Summary:</li><li>Short in P3 bus.</li></ul>
	Request to get quad in transfer hall. It would reduce losses -
	lose 20% of beam.
	Requests:
0	MiniBooNE
	■ Summary:
	<ul> <li>Waiting for stable high intensithy beam from booster</li> </ul>
	<ul><li>Requests:</li></ul>
0	NuMI
	• Summary:
	<ul> <li>Leak checked target chase and it looked good.</li> </ul>
	<ul> <li>Started up munter units and did initial balancing</li> </ul>
	Electricians still downstairs.     Sc tasts completed last pickts.
	<ul><li>SS tests completed last nights.</li><li>Requests:</li></ul>
0	CDF

	<ul> <li>Summary:         <ul> <li>Finished replacing 400 T hilman roller</li> <li>Problems with COT. 2 cells that were noisy. Activity may go as late as Wed. morning.</li> <li>Last detector on flammable gas.</li> <li>Pair of counters in B11 that need to be removed</li> </ul> </li> <li>Requests:</li> </ul>
0	D0
	<ul> <li>Summary:         <ul> <li>Detector is now completely closed.</li> <li>Commissioning all systems</li> <li>One glitch where we lost mycomm helium due to problem with strainers.</li> </ul> </li> </ul>
	Requests:
0	FESS
	Summary:
	<ul><li>Tev cooldown to 4.5 K completed</li><li>Want to do a Cryo cooldown.</li></ul>
	Requests:
0	EE Support
	Summary:
	Requests:
0	Other
	Summary:
	Requests:
o P	lan
e P	iaii

• The

- Summary:

  - Access day.

    If possible, turn back on during day shift.

    Goal is to get beam to Pbar for holiday weekend.

    Get holiday call-in lists to Mary.
- Requests: